

PIC16F87/88 Rev. B1 Silicon Errata

The PIC16F87/88 Rev. B1 parts you have received conform functionally to the Device Data Sheet (DS30487C), except for the anomalies described below.

All of the issues listed here will be addressed in future revisions of the PIC16F87/88 silicon.

The following silicon errata apply only to PIC16F87/88 devices with these Device/Revision IDs:

Part Number	Device ID	Revision ID
PIC18F87	00 0111 001	0 0101
PIC16F88	00 0111 011	0 0101

The Device IDs (DEVID1 and DEVID2) are located at addresses 3FFFEh:3FFFFh in the device's configuration space. They are shown in binary in the format "DEVID2 DEVID1".

1. Module: Internal RC Oscillator

A high Sleep current will exist when the following condition is met and procedures are followed:

CONDITION: FOSC<2:0> (Configuration Word 1 Register) bits are configured for any oscillator selection other than the internal RC oscillator.

PROCEDURE:

1. Clock switch occurs anywhere in the application code where the internal RC oscillator is selected via the SCS bits ('10').
2. Sleep mode is entered while the SCS bits are configured for the internal RC oscillator ('10').

Work around

Before Sleep mode is entered, configure or clear the SCS bits ('00') to switch back to the primary clock source that is defined by FOSC<2:0> (Configuration Word 1 Register).

Date Codes that pertain to this issue:

All date codes associated with silicon revision B1. This issue is not found in devices with silicon revision C2 (Revision ID 01000) or later.

PIC16F87/88

2. Module: Internal RC Oscillator IOFS bit

The device data sheet states when an INTOSC frequency is selected (125, 250, 500 kHz; 1, 2, 4, 8 MHz), the frequency will be stable when the IOFS bit becomes set (IOFS = 1) at 4 ms. The following applies for applications relying on time dependent code.

Under the following conditions, any of the INTOSC frequencies may not be stable when IOFS becomes set (IOFS = 1). Devices may vary from one to the next and may take as long as 60 ms to become stable.

1. Wake from Sleep, internal RC oscillator is selected via the SCS bits or Configuration Word 1 and the IRCF bits are configured for an INTOSC frequency.
2. POR is executed, internal RC oscillator is selected via the SCS bits or Configuration Word 1 and the IRCF bits are configured for an INTOSC frequency.

3. The INTRC (31.25 kHz) is clocking the device and a switch to an INTOSC frequency is executed via modification of the IRCF bits.
4. An alternative oscillator selection is clocking the device (i.e., HS mode) and a clock switch to the internal RC oscillator is executed via the SCS bits with the IRCF bits configured for an INTOSC frequency.

Work around

Implement the following software delay shown in Example 1 after an INTOSC frequency has been enabled and before any frequency dependent application code is executed. This routine will delay application execution approximately 2K-150K T_{cy} (instruction cycles are dependent upon the INTOSC frequency) to ensure a stable INTOSC frequency.

Date Codes that pertain to this issue:

All date codes associated with silicon revision B1. This issue is not found in devices with silicon revision C2 (Revision ID 01000) or later.

EXAMPLE 1: DELAY ROUTINE

```
DlyVarH    equ    <define address based on application requirements>
DlyVarL    equ    <define address based on application requirements>

;Load the delay variable DlyVarH with the following value for the selected frequency:
;125kHz    0x0300
;250kHz    0x0600
;500kHz    0x0C00
;1MHz      0x1900
;2MHz      0x3100
;4MHz      0x6200

delay                                ;insure the correct data memory bank is selected
                                        ; for access of data variables
    CLRF    DlyVarL                    ;initialize low delay variable
    MOVLW   0x62                        ;initialize high delay variable
    MOVWF   DlyVarH

dly_loop
    DECFSZ  DlyVarL,f                    ;decrement low variable
    GOTO    dly_loop
    DECFSZ  DlyVarH,f                    ;decrement high variable
    GOTO    dly_loop
RETURN                                ;delay done
```

3. Module: Internal RC Oscillator

When any one of the seven INTOSC frequencies is enabled by the following conditions, it is possible for the oscillator to overshoot the selected frequency:

1. A clock switch from INTRC (31 kHz) to an INTOSC (125 kHz-8 MHz) frequency via the IRCF bits (OSCCON register).
2. Exit from Sleep mode with the IRCF bits already configured for an INTOSC frequency.
3. Executing a clock source switch via the SCS bits (OSCCON register) to the internal RC oscillator with the IRCF bits already configured for an INTOSC frequency.

If the selected frequency is 8 MHz, then the voltage versus frequency specification of the device may be violated.

Work around

When it is required for the application to run at 8 MHz, it is recommended that the application does not start executing code at 8 MHz until the 60 ms firmware delay (see issue 2) has completed. During the 60 ms settling period, the application can execute code up to 4 MHz. Upon completion of the 60 ms firmware delay, the 8 MHz can be selected via the IRCF bits.

Date Codes that pertain to this issue:

All date codes associated with silicon revision B1. This issue is not found in devices with silicon revision C2 (Revision ID 0 1000) or later.

4. Module: PORTB Pull-ups

When $\overline{RBPU} = 0$ (OPTION_REG register), the PORTB weak pull-ups will not be disabled by the input functions of the SSP and/or CCP (Capture mode) module as indicated by the RB<5:1> I/O block diagrams in **Section 5.0 "I/O Ports"**.

Work around

1. If the SSP and/or CCP (Capture mode) module is enabled, do not enable the PORTB weak pull-ups and use external pull-up resistors.

OR

2. If the SSP and/or CCP (Capture mode) module and PORTB pull-ups are enabled, then evaluate the functionality of the SSP (I²C™/SPI) or CCP (Capture mode) module to ensure proper operation within your application.

Date Codes that pertain to this issue:

All date codes associated with silicon revision B1. This issue is not found in devices with silicon revision C2 (Revision ID 0 1000) or later.

5. Module: PORTB

A delay of 1 T_{osc} will occur if an instruction that modifies the contents of PORTB simultaneously occurs when any of the following modules (if enabled) execute an operation that effects the signals on their respective PORTB I/O pins.

CCP Module:

PWM Mode (CCP1CON<3:0> = 11xx)

When CCP1CON<5:4> bits = 10, the PWM output signal will be delayed by 1 T_{osc} when an instruction to modify the contents of PORTB is executed.

SSP Module:

SPI Slave Modes (SSPCON<3:0> = 0100 and 0101)

Clock signal is derived from an external source. Transmission of data (SDO pin) will be delayed by 1 T_{osc} when an instruction to modify the contents of PORTB is executed. Reception of data is not affected.

AUSART Module:

Synchronous Slave Mode (TXSTA<7> = 0)

Clock signal is derived from an external source. Transmission of data (TX pin) will be delayed by 1 T_{osc} when an instruction to modify the contents of PORTB is executed. Reception of data is not affected.

Work around

None

Date Codes that pertain to this issue:

All date codes associated with silicon revision B1. This issue is not found in devices with silicon revision C2 (Revision ID 0 1000) or later.

PIC16F87/88

6. Module: PORTB, RB6 Pin

During normal operating conditions, extra current will be consumed on the PIC16F87/88 device's power source (V_{DD}) when the PORTB, RB6 pin is configured as an analog input (AN5) and is connected to an analog source. A/D operation on RB6 or any of the other analog I/O pins will not be affected by this extra current. The extra current is due to the T1CKI Schmitt Trigger not being disabled when RB6 is configured as an analog pin. The amount of additional current observed will be dependent on the analog voltage present on the AN5 pin. The following table illustrates this additional current across operating temperatures:

	Max	Units	Conditions	
All Devices	1.4	mA	-40°C	$V_{DD} = 5.5V$ AN5 = 0.6-0.7 V_{DD}
	1.3	mA	+25°C	
	1.1	mA	+85°C	
Extended Devices	0.9	mA	+125°C	

Work around

None

Date Codes that pertain to this issue:

All date codes associated with silicon revision B1. This issue is not found in devices with silicon revision C2 (Revision ID 0 1000) or later.

7. Module: PORTB Interrupts

When the PORTB interrupt-on-change feature and a PORTB peripheral are enabled simultaneously, the PORTB peripheral input signal's rising and falling edges will trigger an interrupt-on-change event. This is due to the interrupt-on-change feature not being disabled on the respective pin for that peripheral when it is enabled.

The affected pins and peripheral signals on PORTB are RB4: SCK and SCL, RB5: \overline{SS} and RB6: T1CKI. The functionality of T1OSI (RB7), T1OSO (RB6) and TX/CK (RB5) is not affected by this issue.

Work around

None

Date Codes that pertain to this issue:

All date codes associated with silicon revision B1. This issue is not found in devices with silicon revision C2 (Revision ID 0 1000) or later.

8. Module: Oscillator Configurations (OSCTUNE Register)

The Device Data Sheet has been revised to reflect changes in the operation of the OSCTUNE register, beginning with silicon Revision C0. The following text and table describe that register's implementation for silicon Revision B1.

The OSCTUNE register adjusts the frequencies of the INTOSC and INTRC clock sources.

OSCTUNE bit 0 is implemented. When the register is modified, the INTOSC and INTRC frequencies begin shifting to the new frequency. The INTRC clock reaches the new frequency within eight clock cycles (approximately $8 * 32 \mu\text{s}$ or $256 \mu\text{s}$).

Work around

N/A

Date Codes that pertain to this issue:

All date codes associated with silicon revision B1. This issue is not found in devices with silicon revision C2 (Revision ID 0 1000) or later.

REGISTER 4-1: OSCTUNE: OSCILLATOR TUNING REGISTER (ADDRESS 90h)

U-0	U-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0
—	—	TUN5	TUN4	TUN3	TUN2	TUN1	TUN0
bit 7							bit 0

Legend:

R = Readable bit
-n = Value at POR

W = Writable bit
'1' = Bit is set

U = Unimplemented bit, read as '0'
'0' = Bit is cleared
x = Bit is unknown

bit 7-6 **Unimplemented:** Read as '0'

bit 5-0 **TUN<5:0>:** Frequency Tuning bits

011111 = Maximum frequency

011110 =

•

•

•

000001 =

000000 = Center frequency. Oscillator module is running at the calibrated frequency.

111111 =

•

•

•

100000 = Minimum frequency

PIC16F87/88

REVISION HISTORY

Rev A Document (9/2003)

First revision of this document. Data Sheet Clarification issue 1 (Voltage Reference Specifications).

Rev B Document (2/2004)

Added Data Sheet Clarification issue 2 (Timer1 Oscillator and In-Circuit Serial Programming).

Rev C Document (4/2004)

Added silicon issue 1 (Internal RC Oscillator).

Rev D Document (6/2004)

Updated silicon issue 1 (Internal RC Oscillator) and added Data Sheet Clarification issue 3 (DC Characteristics).

Rev E Document (9/2004)

Added silicon issue 2 (Internal RC Oscillator IOFS bit) and 3 (PORTB Pull-ups).

Rev F Document (10/2004)

Amended silicon issue 1 (Internal RC Oscillator) and 2 (Internal RC Oscillator IOFS bit), added new issue 3 (Internal RC Oscillator), renumbered existing issue 3 to issue 4 (PORTB Pull-ups) and added issue 5 (PORTB).

Rev G Document (2/2005)

Removed Data Sheet Clarification issues.

Rev H Document (4/2005)

Added silicon issue 6 (PORTB, RB6 pin).

Rev J Document (6/2005)

Added silicon issue 7 (PORTB Interrupts).

Rev K Document (9/2006)

Annotated all silicon issues to show resolution in subsequent silicon revisions of this device.

Rev L Document (1/2008)

Added silicon issue 8 (Oscillator Configurations, OSCUNE Register).

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, rPIC and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, PICkit, PICDEM, PICDEM.net, PICtail, PIC³² logo, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rLAB, Select Mode, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2008, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==**

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta

Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston

Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago

Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas

Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit

Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo

Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles

Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara

Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto

Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-4182-8400
Fax: 91-80-4182-8422

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama
Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-572-9526
Fax: 886-3-572-6459

Taiwan - Kaohsiung
Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820